

**Environmental Management
Water Management Operations
River Engineering Team**

Date of Issue: 23 April 2008

**22 April 2008 – North Saskatchewan River at Edmonton
2007/2008 – Observation Report No. 1**

Ice conditions on the North Saskatchewan River at Edmonton near KM 339.6 were documented by Alberta Environment on Tuesday, 22 April 2008. Photos of the river were taken from the High Level Bridge crossing looking both upstream and downstream. Unless changing river conditions warrant further documentation, no additional observation reports will be issued.



Photo 1: Looking upstream from the High Level Bridge. (22 April 2008)



Photo 2: Looking upstream and towards the right bank. (22 April 2008)



Photo 3: Looking downstream from the High Level Bridge. (22 April 2008)



Photo 4: Looking downstream and towards the right bank. (22 April 2008)




Photo 5: Looking downstream along the left bank and border ice. (22 April 2008)